



## Popcorn Popping Instructions:

1. Use a sturdy table.
2. Plug it in, turn on light and heat kettle switches.
3. Let the machine warm up for 5 minutes.
4. Turn on the kettle motor.
5. Put oil in first, then add the kernels.
6. Once popcorn popping slows down, dump kettle by pulling down the black knob.
7. Put in the next batch immediately.
8. Repeat steps 5 and 6.
9. ***\*\*When you are on your last batch of popcorn shut off heat kettle 10 seconds after your first popped piece of popcorn falls out.\*\****  
  
***\*\*\*\*\*If not the machine will smoke.\*\*\*\*\****
10. When you dump out the last batch of popcorn, shut off kettle motor.

***\*\*When done with the machine, please empty and leave as is. We will clean it for you \*\****